


**ACL Race Series - H = STD / HX = Jeu suppl 0.001"**

Marque	Type Moteur	Coussinets de bielles	Côte	Prix HTVA	Coussinets de vilebrequin	Côte	Prix HTVA	Cales	Côte	Prix HTVA
Alfa Romeo	1570cc, 1779cc, 1962cc, 1995cc Alfetta, Giulia, Giulietta, Spider, GT, 155, 164	4B1110H	Std, .25	68,70 €	5M1112H	Std, .25	138,53 €			
	1290cc 1300				5M1112H	Std, .25	138,53 €			
	JTS V6 3195cc 159, Brera, Spider	6B2270H	Std, .025, .25	123,70 €	4M2273H	Std, .025, .25	268,95 €			
		6B2270HX	Std	123,70 €	4M2273HX	Std	268,95 €			
Audi	1595cc, 1781cc (inc. Turbo), 1984cc A3, A4, A6, TT, 80, 90, 100 (1983-2001)	4B1606H	Std, .025, .25, .50	47,55 €	5M1644H	Std, .25, .50	64,13 €	2T1644	Std	POA
		4B1606HX	Std	47,55 €	5M1644HX	Std	64,13 €			
	1781cc Turbo, 1984cc DOHC (inc. Turbo) A3, A4, A6, TT (2000 -)	4B1609H	Std, .025, .25	57,43 €						
		4B1609HX	Std	57,43 €						
	TFSI 1984cc 4 cyl. ( CDL ) S3, TTS	4B5562H	std, .025, .25	POA						
		4B5562HX	std	POA						
	TFSI 2480cc 5cyl. ( CEPA / CEPB ) TTRS, RS3, RS Q3	1B5562H	std, .025, .25	POA						
		1B5562HX	std	POA						
		4B5562H	std, .025, .25	POA						
		4B5562HX	std	POA						
VR6 3189cc, 3597cc	6B5530H	Std, .025, .25	POA	7M5532H	Std, .025, .25	POA	2T5532	Std	POA	
	6B5530HX	Std	POA	7M5532HX	Std	POA				

Marque	Type Moteur	Coussinets de bielles	Côte	Prix HTVA	Coussinets de vilebrequin	Côte	Prix HTVA	Cales	Côte	Prix HTVA
<b>BMC</b>	Mini 997cc, 998cc 4 cyl.	4B2201H	Std, 001, 010	POA	3M2203H	Std, 001, 010	POA	2T2203	Std	POA
		4B2201HX	Std	POA	3M2203HX	Std	POA	RB843	Semi	POA
	Mini ( up to 1983 ) 1275cc 4 cyl.	4B2206H	Std, 001, 010	POA	3M2204H	Std, 001, 010	POA	2T2204	Std	POA
		4B2206HX	Std	POA	3M2204HX	Std	POA			
	Mini ( fron 1983 on ) 1275cc 4 cyl.	4B2206H	Std, 001, 010	POA	3M2205H	Std, .025, .25	POA	2T2204	Std	POA
		4B2206HX	Std	POA	3M2205HX	Std	POA			
<b>BMW</b>	M40B16/18, M42B18, M43B16/18/19, M44B19 (1.6L, 1.8L, 1.9L) 316, 318, Z3	4B1490H	Std, .025, .25, .50	48,15 €	5M1538H	Std, .025, .25, .50	143,55 €			
		4B1490HX	Std	48,15 €	5M1538HX	Std	143,55 €			
	M20B20/25/27, M50B20/25/27, M52B20/25/28, M54B25 (2.0L, 2.5L, 2.7L, 2.8L)	6B1490H	Std, .025, .25, .50	68,70 €	7M1532H (Après 03/1988)	Std, .025, .25, .50	174,83 €			
		6B1490HX	Std	68,70 €	7M1532HX (Après 03/1988)	Std	174,83 €			
	M54B22, M54B30 (2.2L, 3.0L)	6B1490H	Std, .025, .25, .50	68,70 €						
		6B1490HX	Std	68,70 €						
	S14/7 (2.0L) Moteurs BMW Motorsport Racing uniquement	4B1489H	Std, .025, .25	106,10 €						
		4B1489HX	Std	106,10 €						
	S14B20, S14B23, S14B25 (2.0L, 2.3L, 2.5L) M3 E30	4B1568H	Std, .025, .25	85,60 €						
		4B1568HX	Std	85,60 €						
	S50B30 (3.0L) M3 E36	6B1515H	Std, .025, .25	160,60 €	7M1532H	Std, .025, .25, .50	174,83 €			
		6B1515HX	Std	160,60 €	7M1532HX	Std	174,83 €			
	S50B32 (3.2L) M3 E36	6B1497H	Std, .025, .25	167,98 €	7M1532H	Std, .025, .25, .50	174,83 €			
		6B1497HX	Std	167,98 €	7M1532HX	Std	174,83 €			
	S54B32 (3.2L) M3 E46	6B1569H	Std, .025, .25	157,30 €	7M1532H	Std, .025, .25, .50	174,83 €			
		6B1569HX	Std	157,30 €	7M1532HX	Std	174,83 €			
	S65B40 ( 4.0L ) M3 E90 3999cc V8	8B1580H	Std, .025, .25	POA						
		8B1580HX	Std	POA						
S85B50 ( 5.0L ) M5 E60 4999cc V10	10B1580H	Std, .025, .25	POA							
	10B1580HX	Std	POA							

Marque	Type Moteur	Coussinets de bielles	Côte	Prix HTVA	Coussinets de vilebrequin	Côte	Prix HTVA	Cales	Côte	Prix HTVA	
Ford	BDA/BDB/BDC/BDD etc. Cosworth	4B1060H	Std, 001, 010, 020	47,08 €	5M2152H	Std, 001, 010, 020	105,45 €	1T2152	Std, +005	POA	
		4B1060HX	Std	47,08 €	5M2152HX	Std	105,45 €				
	2.0L Cosworth	4B2166H	Std, .25, .50	46,30 €	5M2167H	Std, .25, .50	62,13 €	2T2167	Std, +005	POA	
		4B2166HX	Std	46,30 €	5M2167HX	Std	62,13 €				
	Ecoboost Turbo 2.0L, 2.3L Turbo ( Mustang, Focus RS )	4B8172H	Std, .25, .50	POA							
		4B8172HX	Std	POA							
	2.0L (LF) Duratec	4B84390H	Std, .025, .25	POA							
		4B4390HX	Std	POA							
	2.3L (L3) Duratec	4B8170H	Std, .025, .25	46,38 €							
		4B8170HX	Std	51,00 €							
1500cc - 1600cc / 4 Cyl Lotus / Ford OVH et Twin Cam (Elan/Escort/Cortina)	4B603H	Std, 001, 010, 020	72,30 €	5M2152H	Std, 001, 010, 020	105,45 €	10C5808 (Twin Cam)	Std	POA		
	4B603HX	Std	72,30 €	5M2152HX	Std	105,45 €	1T2152	Std, +005	POA		
Honda	D15B/D15Z (1493cc) (Moteurs à partir du 09/1991)	4B1956H	Std, .025, .25	50,70 €							
		4B1956HX	Std	55,75 €							
	D16A/D16B/D16W/D16Y/D16Z (1590cc)	4B1956H	Std, .025, .25	50,70 €	5M1957H	Std, .025, .25	76,38 €	1T1957	Std	POA	
		4B1956HX	Std	55,75 €	5M1957HX	Std	84,03 €				
	A18A, ES, ET, A20A (1829cc / 1955cc)	4B1946H	Std, .025, .25	44,00 €							
		4B1946HX	Std	44,00 €							
	B16A (1595cc)	4B1946H	Std, .025, .25	44,00 €	5M1959H	Std, .025, .25	75,53 €	1T1957	Std	POA	
		4B1946HX	Std	44,00 €	5M1959HX	Std	75,53 €				
	B17A1/B18A1/B18B1/B18B2 (1678cc / 1834cc)	4B1946H	Std, .025, .25	44,00 €	5M1959H	Std, .025, .25	75,53 €	1T1957	Std	POA	
		4B1946HX	Std	44,00 €	5M1959HX	Std	75,53 €				
	B18A/B20A SOHC Uniquement (1834cc / 1958cc)	4B1946H	Std, .025, .25	44,00 €	5M1957H	Std, .025, .25	76,38 €	1T1957	Std	POA	
		4B1946HX	Std	44,00 €	5M1957HX	Std	84,03 €				
	Honda	B18C1/B18C2/B18C5/B18C7 (1797cc VTEC)	4B1925H	Std, .025, .25	45,03 €	5M1959H	Std, .025, .25	75,53 €	1T1957	Std	POA
			4B1925HX	Std	45,03 €	5M1959HX	Std	75,53 €			

Marque	Type Moteur	Coussinets de bielles	Côte	Prix HTVA	Coussinets de vilebrequin	Côte	Prix HTVA	Cales	Côte	Prix HTVA
	B20A/B21A/B21A1 DOHC Uniquement (1958cc / 2056cc)	4B1936H	Std, .025, .25	POA	5M1957H	Std, .025, .25	76,38 €	1T1957	Std	POA
		4B1936HX	Std	POA	5M1957HX	Std	84,03 €			
	B20B/B20Z (1972cc)	4B1946H	Std, .025, .25	44,00 €	5M1959H	Std, .025, .25	75,53 €	1T1957	Std	POA
		4B1946HX	Std	44,00 €	5M1959HX	Std	75,53 €			
	D17A/D17Z (1668cc)				5M1957H	Std, .025, .25	76,38 €	1T1957	Std	POA
					5M1957HX	Std	84,03 €			
	K20A3 (1998cc)	4B1906H	Std, .025, .25, .50	39,38 €	5M1959H	Std, .025, .25	75,53 €	1T1957	Std	POA
		4B1906HX	Std	43,30 €	5M1959HX	Std	75,53 €			
	K20A2/K20Z1/K24A/K24Z1 (1998cc / 2354cc)	4B1972H	Std, .025, .25	43,58 €	5M1959H	Std, .025, .25	75,53 €	1T1957	Std	POA
		4B1972HX	Std	43,58 €	5M1959HX	Std	75,53 €			
	F18B/F20B (1850cc / 1997cc)	4B1946H	Std, .025, .25	44,00 €						
		4B1946HX	Std	44,00 €						
	F20A, F22A, F22B (1997cc / 2156cc)	4B1936H	Std, .025, .25	0,00 €						
		4B1936HX	Std	0,00 €						
	F20C/F22C (1997cc / 2157cc)	4B1912H	Std, .025, .25	58,68 €	5M1913H	Std, .025, .25	75,75 €			
		4B1912HX	Std	58,68 €	5M1913HX	Std	83,33 €			
	H22A/H22Z (2157cc)	4B1912H	Std, .025, .25	58,68 €	5M1957H	Std, .025, .25	76,38 €	1T1957 (1998-)	Std	POA
		4B1912HX	Std	58,68 €	5M1957HX	Std	84,03 €			
	F23A/F23Z (2254cc) (1998-)	4B1906H	Std, .025, .25, .50	39,38 €	5M1957H	Std, .025, .25	76,38 €	1T1957	Std	POA
		4B1906HX	Std	43,30 €	5M1957HX	Std	84,03 €			
Hyundai	G4KF 2.0T (Theta II, 2010 on ) 1998cc 4 cyl. Turbo - Genesis, Sonata	4B1293H	Std, .025, .25	POA	5M1295H	Std, .025, .25	POA			
		4B1293HX	Std	POA	5M1295HX	Std	POA			
Lancia	Delta HF Integrale 1995cc Turbo	4B2904H	Std, .025, .25	82,45 €	5M2908H	Std, .025, .25	154,83 €			
		4B2904HX	Std	82,45 €	5M2908HX	Std	154,83 €			
Lotus	Elise, Exige 2ZZ-GE 1796cc 4 cyl.	4B1856H	Std, .025, .25	POA	5M1857H	Std, .025, .25	POA	1T1853	Std	POA
		4B1856HX	Std	POA	5M1857HX	Std	POA			

Marque	Type Moteur	Coussinets de bielles	Côte	Prix HTVA	Coussinets de vilebrequin	Côte	Prix HTVA	Cales	Côte	Prix HTVA	
<b>Mazda</b>	2.0L LF MZR (Duratec) 3, MX-5	4B4390H	Std, .025, .25	38,90 €							
		4B4390HX	Std	42,78 €							
	2.3L L3 MZR (Duratec) 3, 6, Tribute	4B8170H	Std, .025, .25	46,38 €							
		4B8170HX	Std	51,00 €							
	2.3L L3-VDT DISI Turbo (Duratec) 3 MPS, 6 MPS, CX-7	4B8172H	Std, .025, .25	74,43 €							
		4B8172HX	Std	74,43 €							
	B1, B3, B5, Z5-DE 1.1L, 1.3L, 1.5L					5M8353H	Std, .025, .25, .50	71,35 €	1T8353	Std	POA
						5M8353HX	Std	78,60 €			
B6/B6-T, BP/BP-T, ZL-VE, ZM-DE 1.5L, 1.6L, 1.8L	4B8351H	Std, .025, .25, .50	49,78 €		5M8353H	Std, .025, .25, .50	71,35 €	1T8353	Std	POA	
	4B8351HX	Std	54,78 €		5M8353HX	Std	78,60 €				
<b>Mini (BMW)</b>	W10B16 1598cc One / Cooper	4B2903H	Std, .025, .25	121,53 €							
		4B2903HX	Std	121,53 €							
	W11B16 - Compresseur 1598cc Cooper S	4B2902H	Std, .025, .25	111,05 €							
		4B2902HX	Std	111,05 €							
<b>Mitsubishi</b>	4G30/31/32/33/35/36/37 1.2L, 1.3L, 1.4L, 1.5L, 1.6L, 1.7L, 1.8L	4B1146H	Std, .025, .25	54,28 €	5M1144H	Std, .025, .25	128,90 €				
		4B1146HX	Std	54,28 €	5M1144HX	Std	141,75 €				
	4G61/4G61T/4G62/4G62BT 1.6L, 1.8L	4B1146H	Std, .025, .25	54,28 €	5M1144H	Std, .025, .25	128,90 €				
		4B1146HX	Std	54,28 €	5M1144HX	Std	141,75 €				
	4G63/4G63T/4G64 (1983-1992)	4B1146H	Std, .025, .25	54,28 €	5M1144H	Std, .025, .25	128,90 €				
		4B1146HX	Std	54,28 €	5M1144HX	Std	141,75 €				
	4G63/4G63-T/4G64 (1992 - 1997) - Avec flange	4B1185H	Std, .025, .25	53,03 €	5M1186H	Std, .025, .25	111,75 €				
		4B1185HX	Std	53,03 €	5M1186HX	Std	111,75 €				
	4G63/ 4G63-T/4G64 (1997 - on) - Avec cales latérales	4B1185H	Std, .025, .25	53,03 €	5M1219H	Std, .025, .25	73,35 €	1T1219	Std	POA	
		4B1185HX	Std	53,03 €	5M1219HX	Std	73,35 €				
	<b>Mitsubishi</b>	4G91/4G92/4G93/4G93-T 1.5L, 1.6L, 1.8L	4B8036H	Std, .25	53,85 €	5M8037H	Std, .25	76,38 €	1T8037	Std	POA

Marque	Type Moteur	Coussinets de bielles	Côte	Prix HTVA	Coussinets de vilebrequin	Côte	Prix HTVA	Cales	Côte	Prix HTVA
	4G94 2.0L	4B8050H	Std, .025, .25	64,63 €	5M8037H	Std, .25	76,38 €	1T8037	Std	POA
		4B8050HX	Std	64,63 €						
	4B11T EVOX 2.0L Lancer Evolution	4B1236H	Std, .025, .25	59,80 €	5M1237H	Std, .025, .25	108,83 €	1T1237	Std	POA
		4B1236HX	Std	59,80 €	5M1237HX	Std	108,83 €			
	4M41 Turbo Diesel 3,2L 4 cyl.	4B1800H	Std	POA						
<b>Nissan</b>	CA16, CA18, CA18DET, CA20, CD17 1.6L, 1.7L, 1.8L, 2.0L	4B1630H	Std, .025, .25, .50	49,88 €	5M1633H	Std, .025, .25, .50	128,05 €			
		4B1630HX	Std	49,88 €	5M1633HX	Std	140,85 €			
	CD20, CD20-T Diesel / Turbo Diesel 2.0L				5M1633H	Std, .025, .25, .50	128,05 €			
					5M1633HX	Std	140,85 €			
	KA24DE 2389cc 4 cyl. ( 240SX )	4B2746H	Std, .025, .25	POA	5M2747H	Std, .025, .25	POA	RB4105	Std	POA
		4B2746HX	Std	POA	5M2747HX	Std	POA			
	MR16DDT 1.6L Turbo				5M2905H	Std, .025, .25	97,88 €			
					5M2905HX	Std	97,88 €			
	RB20E, RB20S SOHC 2.0L 6 Cyl				7M2394H	Std, .025, .25, .50	141,95 €	RB4107	Std	POA
					7M2394HX	Std	141,95 €			
	RB20DE, RB20DET DOHC 2.0L 6 Cyl	6B2630H	Std, .025, .25	69,50 €	7M2394H	Std, .025, .25, .50	141,95 €	RB4074	Std	POA
		6B2630HX	Std	69,50 €	7M2394HX	Std	141,95 €			
	RB25DE, RB25DETT 2.5L 6 Cyl	6B2960H	Std, .025, .25, .50	73,23 €	7M2394H	Std, .025, .25, .50	141,95 €	RB4074	Std	POA
		6B2960HX	Std	73,23 €	7M2394HX	Std	141,95 €			
	RB26DETT 2.6L 6 Cyl	6B2960H	Std, .025, .25, .50	73,23 €	7M2428H	Std, .025, .25, .50	170,15 €	RB4074	Std	POA
		6B2960HX	Std	73,23 €	7M2428HX	Std	170,15 €			
	RB30E, RB30ET 3.0L 6 Cyl	6B2390H	Std, .025, .25, .50	68,53 €	7M2394H	Std, .025, .25, .50	141,95 €	RB4074	Std	POA
		6B2390HX	Std	68,53 €	7M2394HX	Std	141,95 €			
<b>Nissan</b> RD28, RD28E, RD28T 3.0L 6 Cyl Diesel, Turbo Diesel				7M2394H	Std, .025, .25, .50	141,95 €				
				7M2394HX	Std	141,95 €				

Marque	Type Moteur	Coussinets de bielles	Côte	Prix HTVA	Coussinets de vilebrequin	Côte	Prix HTVA	Cales	Côte	Prix HTVA
Nissan	SR20DE, SR20DET (Non GTiR) 2.0L	4B2960H (17mm)	Std, .025, .25, .50	50,70 €	5M2964H	Std, .025, .25, .50	91,20 €	1T2964	Std	POA
		4B2960HX (17mm)	Std	50,70 €	5M2964HX	Std	91,20 €			
	SR20DET (GTiR) 2.0L	4B2976H (19mm)	Std, .025, .25	47,78 €	5M2975H (5 trous huile sup)	Std, .025, .25	99,38 €	1T2964	Std	POA
		4B2976HX (19mm)	Std	52,55 €	5M2975HX	Std	109,33 €			
	TB42/TB45/TB48 L6 4.2L, 4.5L, 4.8L 6 Cyl	6B2955H	Std, .025, .25	87,55 €						
		6B2955HX	Std	87,55 €						
	TD25, TD27 ( Navara ) 2494cc, 2663cc 4 cyl. Diesel	4B2966H	Std, .025, .25	POA	5M2965H	Std, .025, .25	POA	2T1367	Std	POA
		4B2966HX	Std	POA	5M2965HX	Std	POA			
	TD42 ( Patrol ) 4169cc 6 cyl. Diesel	6B2966H	Std, .025, .25	POA	7M2965H	Std, .025, .25	POA	2T1367	Std	POA
		6B2966HX	Std	POA	7M2965HX	Std	POA			
	VG20E, VG20ET, VG20DET 2.0L V6				4M2737H	Std, .025, .25	137,78 €			
					4M2737HX	Std	151,55 €			
	VG30E, VG30ET, VG30i, VG33E 3.0L, 3.3L V6	6B2390H	Std, .025, .25, .50	68,53 €	4M2737H	Std, .025, .25, .50	137,78 €			
		6B2390HX	Std	68,53 €	4M2737HX	Std	151,55 €			
	VG30DE, VG30DETT 3.0L V6	6B2390H	Std, .025, .25, .50	68,53 €	4M2737H	Std, .025, .25, .50	137,78 €			
		6B2390HX	Std	68,53 €	4M2737HX	Std	151,55 €			
	VQ20DE, VQ25DE, VQ25DET, VQ30DE, VQ30DET 2.0L, 2.5L, 3.0L V6	6B2630H	Std, .025, .25	69,50 €	4M2633H	Std, .025, .25	71,40 €	2T2633	Std	POA
		6B2630HX	Std	69,50 €	4M2633HX	Std	78,55 €			
	VQ35DE 3.5L V6	6B2640H	Std, .025, .25	83,70 €	4M2633H	Std, .025, .25	71,40 €	2T2633	Std	POA
		6B2640HX	Std	83,70 €	4M2633HX	Std	78,55 €	6RB4128 (Jeu de 6)		POA
VR38DETT (GTr-R35) 3.8L V8 Twin Turbo	1B2500H	Std-0/1/2 (Graded)	48,18 €	1M2505H	Std-0/1/2/3/4 (Graded)	62,93 €	1T2505	Std	46,50 €	
	6B2500H	Std, .25	POA	4M2505H	Std, .25	202,40 €				
VK45, VK50, VK56 4.5L, 5.0L, 5.6L V8	8B2990H	Std, .025, .25	207,25 €	5M2995H	Std, .025, .25	179,98 €	2T2995	Std	45,48 €	
	8B2990HX	Std	207,25 €	5M2995HX	Std	179,98 €				
ZD30, QD32 2953cc, 3153cc 4 Cyl Diesel	4B2966H	Std, .025, .25	POA	5M2965H	Std, .025, .25	POA	2T1367	Std		
	4B2966HX	Std	POA	5M2965HX	Std	POA				

Marque	Type Moteur	Coussinets de bielles	Côte	Prix HTVA	Coussinets de vilebrequin	Côte	Prix HTVA	Cales	Côte	Prix HTVA
Opel	1.6L, 1.8L, 2.0L, 2.4L Family II	4B2322H	Std, .025, .25, .50	51,95 €						
		4B2322HX	Std	57,15 €						
	Z28NEL, Z28NET, Z32SE 2.8L Turbo, 3.2L V6	6B2270H	Std, .025, .25	123,70 €	4M2273H	Std, .025, .25	268,95 €			
		6B2270HX	Std	123,70 €	4M2273HX	Std	268,95 €			
Peugeot	XU9/XU10/XU10J2/XU10J4/XU10M 1905cc, 1998cc	4B7700H	Std, .25	61,05 €						
	XU7JB, XU7JP, XU7JP4 1761cc	4B7736H	Std, .30	79,93 €						
	TU9, XV3, XV5, XV8 954cc	4B7712H	Std, .30, .50	44,85 €				1T7707	Std, +.15	POA
		4B7712HX	Std	49,30 €						
	TU3.2/TU3J2/TU5JP/TU5JP4 1360cc, 1587cc	4B7712H	Std, .30, .50	44,85 €	5M2797H	Std, .30, .50	50,70 €	1T7707	Std, +.15	POA
		4B7712HX	Std	49,30 €	5M2797HX	Std	55,75 €			
	TU1, TU2.4, TU2J2, XW3, XW7 1124cc, 1294cc	4B7712H	Std, .30, .50	44,85 €				1T7709	Std, +.10	POA
		4B7712HX	Std	49,30 €						
	TU3A, TU3CP, TU3M, TU3S, XY6, XY7, XY8 1360cc	4B7712H	Std, .30, .50	44,85 €				1T7709	Std, +.10	POA
		4B7712HX	Std	49,30 €						
	TU1JP, TU3JP, TU5J2, TU5J4, XU5J, XU5JP 1124, 1360, 1580, 1587cc	4B7712H	Std, .30, .50	44,85 €	5M2797H	Std, .30, .50	50,70 €	1T7709	Std, +.10	POA
		4B7712HX	Std	49,30 €	5M2797HX					
	TU3JP (2005 -) TUD5 Diesel 1360cc, 1587cc				5M2797H	Std, .30, .50	50,70 €	1T7709	Std, +.10	POA
					5M2797HX	Std				
EW7, EW10, EW12 1749cc, 1997cc, 2230cc	4B7736H	Std, .30	79,93 €							



Marque	Type Moteur	Coussinets de bielles	Côte	Prix HTVA	Coussinets de vilebrequin	Côte	Prix HTVA	Cales	Côte	Prix HTVA	
Porsche	911 / 914 (Inc. Turbo) 1964 -1971 1990cc, 2193cc H6	6B2452H	Std, .025, .25	81,00 €							
		6B2452HX	Std	83,55 €							
	911 / 930 1971 -1977 2341cc / 2687cc / 2994cc H6	6B2455H	Std, .025, .25	POA							
		6B2455HX	Std	POA							
	911 1978- 1989 2993cc / 3164cc H6	6B2462H	Std, .025, .25	POA							
		6B2462HX	Std	POA							
	930 1978 -1989 3299cc H6	6B2463H	Std, .025, .25	POA							
		6B2463HX	Std	POA							
	911 ( 964, 993 ) 1989 -1997 3600cc, 3746cc H6	6B2463H	Std, .025, .25	POA							
		6B2463HX	Std	POA							
	Renault	129-5, XZ7R, 150-X5J 1219cc, 1360cc	4B7712H	Std, .30, .50	44,85 €						
			4B7712HX	Std	49,30 €						
F1N, F2N, F2R, F3N, F3P,F3R, F4R, F7P, F7R 1721cc, 1794cc, 1763cc, 1998cc		4B7820H	Std, .25, .50	44,40 €	5M7807H	Std, .25, .50	64,33 €	1T7807	Std, +.10	POA	
		4B7820HX	Std	44,40 €	5M7807HX	Std	64,33 €	RB4122	Semi		
F8M, F8Q 1595cc, 1870cc Diesel		4B7820H	Std, .25, .50	44,40 €	5M7807H	Std, .25, .50	64,33 €	1T7807	Std, +.10	POA	
		4B7820HX	Std	44,40 €	5M7807HX	Std	64,33 €				
Saab	B202/3/5/6, B235/5 1395cc, 2290cc 4 cyl. ( Turbo incl. )	4B2010H	Std, .25	POA	5M2015H	Std, .25	POA				
	LP9 2.8L Turbo V6 9-3, 9-5	6B2270H	Std, .025, .25	123,70 €	4M2273H	Std, .025, .25	268,95 €				
		6B2270HX	Std	123,70 €	4M2273HX	Std	268,95 €				
Subaru	EJ15, EJ16 1493cc, 1597cc	4B8296H (Pour dia 52mm)	Std, .025, .25, .50	48,18 €	5M8297H (Cale #3 pos)	Std, .025, .25, .50	108,60 €				
		4B8296HX	Std	48,18 €	5M8297HX	Std	108,60 €				
		4B8320H (Pour dia 48mm)	Std, .025, .25, .50	43,03 €							
		4B8320HX	Std	43,03 €							

Marque	Type Moteur	Coussinets de bielles	Côte	Prix HTVA	Coussinets de vilebrequin	Côte	Prix HTVA	Cales	Côte	Prix HTVA	
Subaru	EJ18E, EJ20, EJ22, EJ25, EJ20T, EJ20TT, EJ22T, EJ25T (Turbo / Twin Turbo) 1820cc, 1994cc, 2212cc, 2457cc H4	4B8296H (Pour dia 52mm)	Std, .025, .25, .50	48,18 €	5M8297H (Cale #3 pos)	Std, .025, .25, .50	108,60 €	RB4125		POA	
		4B8296HX	Std	48,18 €	5M8897HX	Std	108,60 €				
		4B8320H (Pour dia 48mm)	Std, .025, .25, .50	43,03 €	5M8309H (Cale #5 pos)	Std, .025, .25, .50	117,23 €				
		4B8320HX	Std	43,03 €	5M8309HX	Std	117,23 €				
	FA20 (BRZ) 1998cc Flat 4	4B8310H	Std, .025, .25	POA							
		4B8310HX	Std	POA							
Suzuki	GSX-R1000 988cc, 999cc	4B8430H	Std, .25, .50	POA							
		4B8430HX	Std	POA							
	Hayabusa 1299cc	4B8431H	Std, .25, .50	POA							
		4B8431HX	Std	POA							
	G13A, G13B, G13BA, G13BB 1298cc, 1324cc	4B8336H	Std, .25, .50	39,38 €	5M8337H	Std, .25, .50	59,93 €	1T8337	Std	POA	
		4B8336HX	Std	43,30 €	5M8337HX	Std	59,93 €				
	M16A Liana, Grand Vitara, Swift 1586cc	4B8440H	Std, .025, .25	73,93 €	5M8443H	Std, .025, .25	122,15 €				
		4B8440HX	Std		5M8443HX	Std	122,15 €				
	Toyota	2A, 3A, 4A, 5A, 6A, 7A 1298cc, 1397cc, 1452cc, 1587cc, 1762cc				5M1695H (Moteurs 01/1983 -)	Std, .025, .25, .50	73,35 €	2T1695	Std	POA
						5M1695HX (Moteurs 01/1983 -)	Std	80,68 €			
4AGE, 4A-GZE, 4A-GEC, 4A-GELC 1587cc		4B1780H	Std, .025, .25, .50	48,63 €	5M1695H	Std, .025, .25, .50	73,35 €	2T1695	Std	POA	
		4B1780HX	Std	48,63 €	5M1695HX	Std	80,68 €				
4AU-GSE (86) 1998cc Flat 4		4B8310H	Std, .025, .25	POA							
		4B8310HX	Std	POA							
2ZZ-GE 1796cc		4B1856H	Std, .025, .25	88,80 €	5M1857H	Std, .025, .25	146,58 €	1T1853	Std	POA	
		4B1856HX	Std	88,80 €	5M1857HX	Std	146,58 €				
2GR-FE 3456cc V6		6B8466H	Std, .025, .25	POA	4M8468H	Std, .025, .25	POA	2T8468	Std	POA	
		6B8466HX	Std	POA	4M8468HX	Std	POA				
1S, 2S, 3S, 4S, 5S 1832cc, 1838cc, 1995cc, 1998cc, 2164cc					5M8361H	Std, .025, .25, .50	92,05 €	2T1689	Std	POA	
					5M8361HX	Std	101,23 €				

Marque	Type Moteur	Coussinets de bielles	Côte	Prix HTVA	Coussinets de vilebrequin	Côte	Prix HTVA	Cales	Côte	Prix HTVA
Toyota	3SGE, 3SGTE 1998cc	4B8366H	Std, .025, .25, .50	57,08 €	5M8361H	Std, .025, .25, .50	92,05 €	2T1689	Std	POA
		4B8366HX	Std	62,78 €	5M8361HX	Std	101,23 €			
	1AZ-FE, 2AZ-FE, 2AZ-FXE 1998cc, 2362cc	4B8411H	Std, .025, .25	47,23 €	5M8412H	Std, .025, .25	79,30 €	1T8412	Std	POA
		4B8411HX	Std	47,23 €	5M8412HX	Std	79,30 €			
	1JZGE, 1JZGTE, 2JZGE, 2JZGTE 2492cc, 2997cc	6B8100H	Std, .025, .25	82,38 €	7M8103H	Std, .025, .25	148,68 €	2T8103	Std	POA
		6B8100HX	Std	82,38 €	7M8103HX	Std	148,68 €			
	1UZFE 3969cc V8	8B8091H	Std, .025, .25, .50	93,70 €	5M8088H	Std, .025, .25, .50	111,28 €	2T8092	Std	POA
		8B8091HX	Std	103,10 €	5M8088HX	Std	111,28 €			
					5M8092H (Remplacement)	Std, .025, .25, .50	111,28 €			
					5M8092HX (Remplacement)	Std	122,38 €			
	2UZFE, 3UZFE 4664cc, 4293cc V8	8B8091H	Std, .025, .25, .50	93,70 €	5M8088H	Std, .025, .25, .50	111,28 €	2T8092	Std	POA
		8B8091HX	Std	103,10 €	5M8088HX	Std	111,28 €			
	1FZFE Landcruiser 4476cc	6B7990H	Std, .025, .25	100,70 €	7M7989H	Std, .025, .25	174,40 €	2T7989	Std	POA
		6B7990HX	Std	100,70 €	7M7989HX	Std	174,40 €			
	1GR-FE Landcruiser, Tundra 3456cc V6	6B7990H	Std, .025, .25	0,00 €	7M7989H	Std, .025, .25	0,00 €	2T7989	Std	POA
		6B7990HX	Std	0,00 €	7M7989HX	Std	0,00 €			
	1HZ Landcruiser 4164cc 6 Cyl Diesel	6B8396H	Std, .025, .25	POA	7M8397H	Std, .025, .25	POA			
		6B8396HX	Std	POA	7M8397HX	Std	POA			
	1RZ, 2RZ, 2TZ, 3RZ 1998CC, 2438CC, 2693CC 4 cyl.	4B8376H	Std, .025, .25	POA	5M8378H	Std, .025, .25	POA	2T8377		
		4B8376HX	Std	POA	5M8378HX	Std	POA			

Marque	Type Moteur	Coussinets de bielles	Côte	Prix HTVA	Coussinets de vilebrequin	Côte	Prix HTVA	Cales	Côte	Prix HTVA	
Volkswagen	1595cc, 1781cc (inc. Turbo), 1984cc, 1998cc Polo, Caddy, Golf, Jetta, Passat (1983-2003)	4B1606H	Std, .025, .25, .50	47,55 €	5M1644H	Std	64,13 €	2T1644	Std	POA	
		4B1606HX	Std	47,55 €	5M1644HX	Std	64,13 €				
	1781cc Turbo, 1984cc (Inc Turbo) Polo, Golf, Jetta, EOS, Passat (2000-)	4B1609H	Std, .025, .25	57,43 €							
		4B1609HX	Std	57,43 €							
	TFSI 1984cc 4 cyl. Golf R	4B5562H	std, .025, .25	POA							
		4B5562HX	std	POA							
	VR6 2792cc, 2861cc, 3189cc, 3597cc	6B5530H	Std, .025, .25	POA		7M5532H	Std	POA			
		6B5530HX	Std	POA		7M5532HX	Std	POA			
Volvo	B200, B204, B230, B234 (Inc Turbo) 1986cc, 2316cc	4B2276H	Std	81,10 €							